

Cut, Weld and Bend Materials Reference Manual

Table of Contents

1	General Safety Information	9
1.1	The Law at Work	9
1.1.1	Occupational Health and Safety Act 2004	11
1.1.2	Dangerous Goods (Storage and Handling) Regulations 2000 Site Assessment.....	14
1.1.3	Oxy/Fuel Legislation	15
1.1.4	Arc/MIG/TIG Legislation.....	19
1.2	General Policies and Procedures	22
1.2.1	Personal Protective Equipment.....	22
1.2.2	Fires and Unplanned Explosions.....	25
1.2.3	Environmental Incidents and Correct Disposal Techniques.....	29
1.2.4	Safety Signs.....	30
1.2.5	Risk Assessment.....	31
1.2.6	Issue Resolution Form	32
1.2.7	Isolation Systems	34
1.2.8	Tag and Lockout.....	37
1.2.9	Work from Heights	38
1.2.10	Confined Space Entry.....	38
1.3	Employee Responsibilities	40
1.3.1	Employee Safety Rules.....	40
1.3.2	Workplace Behaviour	41
1.3.3	Alcohol and Illicit Drugs.....	41
1.4	Arc Safety	42
1.4.1	Welding Safety Summary	42
1.4.2	Burns and Fire	43
1.4.3	Fire Hazards	44
1.4.4	Fumes and Gases.....	46
1.4.5	Ventilation.....	46
1.4.6	Health Effects of Fumes.....	47
1.4.7	Electric Shock	50
1.4.8	Electrocution	51
1.4.9	Welding Procedure – Water and Damp Areas	52
1.4.10	Electrocution Rescue.....	53
1.4.11	Personal Safety Precautions For Electric/Arc Welding	55
1.4.12	Safety Practices and Procedures	55
1.4.13	Manual Handling	56
1.4.14	Slips, Trips and Falls	57

**Cut, Weld and Bend Materials
Reference Manual**

2	Equipment Knowledge	60
2.1	Glossary of Terms.....	60
2.1.1	General Terms	60
2.1.2	Capital Terms.....	62
2.1.3	Resource Terms	63
2.1.4	Inventory Terms.....	63
2.2	Safety and Handling of Compressed Gases, Cylinders, Safety Devices and Gas Equipment	65
2.2.1	Oxygen, Compressed (O ₂).....	65
2.2.2	Acetylene, Dissolved (C ₂ H ₂)	68
2.2.3	LPG/Propane/Handigas	71
2.2.4	Manufacturer's Recommended Pressure Settings for Welding, Cutting, and Heating with Oxy and Acetylene	76
2.2.5	Manufacturer's Recommended Pressure Settings for Welding, Cutting and Heating for Oxygen and LPG Cutting.....	77
2.2.6	Flashback Arrestors (AS 4603)	80
2.2.7	Flashback Arrestors	81
2.3	Maintenance	83
2.3.1	Guidance on Maintenance	83
3	Conduct Operations	87
3.1	Set Up, Start Up and Shut Down Procedures.....	87
3.1.1	Oxy/Fuel Gas Set Up Procedure	87
3.1.2	Oxy/Fuel Gas Start Up Procedure	88
3.1.3	Oxy/Fuel Gas Shut Down Procedure	89
3.2	Thermal Heating, Cutting and Gouging Theory.....	90
3.2.1	Introduction.....	90
3.2.2	Process	90
3.2.3	Equipment.....	92
3.2.4	Selection of Tip Size and Gas Pressures	93
3.2.5	Cutting Tips	94
3.2.6	Cutting Torch Guides.....	94
3.2.7	Safe Practices.....	95
3.2.8	Techniques	97
3.2.9	Preparation for Cutting	98
3.2.10	Types of Cuts	99
3.2.11	Cutting Problems and Causes.....	101
3.2.12	Flame Gouging Theory.....	103
3.2.13	Fuel Gases and Process.....	104
3.2.14	Gouging Techniques.....	105

Cut, Weld and Bend Materials Reference Manual

3.2.15	Flame Gouging Applications	107
3.2.16	Gouging Problems	108
3.2.17	OXY, LPG and Acetylene Heating.....	109
3.2.18	LPG Heating	111
3.3	ARC Welding Process.....	112
3.2.1	Welding Types	113
3.3.2	Welding Positions.....	115
3.3.3	Welding Which Can Be Done On Quarry Sites with This Unit.....	116
3.3.4	Welding Faults.....	119
3.3.5	Causes of Welding Faults.....	121
3.3.6	Welding With the Arc	127
3.3.7	Striking the Arc	129
3.3.8	Rate of Travel	131
3.3.9	Making a Straight Run.....	133
3.3.10	Square Edge Butt Joint	134
3.3.11	Effects of Welding	136
3.3.12	Weaving.....	137
3.3.13	Stopping and Restarting a Weld.....	138
3.3.14	Tack Welding	139
3.3.15	Reinforcing a Run	139
3.3.16	Fillet Welds.....	140
3.3.17	Single Pass Fillet.....	142
3.4	Processing Outcomes	151
3.5	Cleaning Up and leaving the Site	152
3.5.1	Leaving Task.....	152
3.5.2	Leaving Site	152
4	Tasks	153
4.1	Task 1: Repairing Broken Handpieces.....	154
4.2	Task 2: Cutting Bolt Holes for Screen Cloths.....	157
4.2.1	Cutting Bolt Holes for Screen Cloth	157
4.3	Task 3: Cutting Bolt Heads Off	158
4.4	Task 4: Hard Facing a Loader Tooth.....	159
4.5	Task 5: Heating and Bending a Length of Steel.....	161

**Cut, Weld and Bend Materials
Reference Manual**

5	Appendices	165
5.1	Acknowledgements	165
5.2	Contacts and Legislation	167
5.2.1	Contacts.....	167
5.2.2	Legislation.....	169
5.3	Sample Risk Management Forms	173
5.3.1	Routine Job Safety Analysis (JSA) Form	173
5.3.2	Issue Resolution Form.....	174
5.4	Hot Works.....	175
5.4.1	Procedure Document for Hot Works	175
5.4.2	Hot Work Permit	176