

Contents

Competency Standard	9
Referenced documents.....	12
Introduction	12
Industry Case Studies	12
Definitions and Terminology.....	13
1. Prepare for laboratory-based acceptance tests	17
1.1 Access relevant job instructions from Laboratory Quality Manual (LQM)	19
1.1.1 <i>Underpinning governance</i>	19
1.1.2 <i>What is a Standard?</i>	19
1.1.3 <i>Document control</i>	20
1.2 Interpret test request to confirm samples to be tested, the test method and equipment involved	21
1.2.1 <i>Test Request form</i>	21
1.2.2 <i>Sample Register</i>	31
1.2.3 <i>Worksheets</i>	32
1.3 Check the accuracy and completeness of accompanying labels and documentation to ensure traceability 36	
1.4 Identify hazards and enterprise controls associated with the sample, preparation methods, reagents and/or equipment	36
1.4.1 <i>Using personal protective equipment</i>	38
1.5 Assemble all required equipment and materials.	39
1.6 Plan work sequences for optimum efficiency and/or throughput of multiple samples	43
2. Prepare samples or test pieces.....	47
2.1 Prepare samples or test pieces	49
2.2 Check that the storage/curing conditions of samples and/or test pieces were appropriate	49
2.3 Compare samples and/or test pieces with test specifications, record observations and report discrepancies.....	50
2.3.1 <i>Non-conformance reporting</i>	50
2.4 Prepare samples and/or test pieces in accordance with appropriate test method	52
2.4.1 <i>Sample Divider – Riffle Splitter</i>	52
2.4.2 <i>Sample preparation requirements</i>	53
2.5 Check test equipment before use	55
2.6 Set up equipment in accordance with test method	56
2.7 Perform pre-use and safety checks in accordance with enterprise procedures	58
2.8 Identify faulty or unsafe equipment and report to appropriate personnel	58
2.9 Check calibration status of instruments and report any out of calibration items to appropriate personnel.....	59
2.9.1 <i>Laboratory Equipment Register</i>	60

3.	Perform laboratory tests.....	63
3.1	Conduct tests in accordance with test method and enterprise procedures	65
3.2	Record data and observations in accordance with enterprise procedures	65
3.2.1	<i>What are the best ways to enter your data?.....</i>	65
3.2.2	<i>What do you do if you make a mistake when entering data?.....</i>	66
3.3	Testing methods.....	67
3.4	Particle Size Distribution	67
3.4.1	<i>What is a particle size distribution test?</i>	67
4.	Typical Tests in accordance with Australian Standards	73
4.1	AS 1289.2.1.6—2005 Method: 2.1.6: Soil moisture content tests	73
4.2	AS 1141.11.1 – 2009 Method 11.1: Particle size distribution—Sieving method.....	75
4.3	AS 1141.15 — 1999 Method 15: Flakiness index	81
4.4	AS 1141.30.1—2009 Method 30.1 Coarse aggregate quality by visual comparison. (Unsound stone).....	86
4.5	AS1141.20.3 – 2000 Method 20.3: Average least dimension Calculation (nomograph).....	93
4.6	Recognise obvious errors or atypical data and take appropriate corrective actions	97
4.7	Perform calculations as set out in test method	98
4.8	Compare calculated results with expected values and report atypical results promptly to appropriate personnel.....	98
4.8.1	<i>Common Calculations.....</i>	99
4.9	Complete technical/administrative records and test reports in accordance with enterprise procedures.....	99
4.9.1	<i>Maintain enterprise Confidentiality standards.....</i>	100
4.10	Seek advice to deal with any situation beyond own technical competence.....	100
5.	Maintain a safe work environment	103
5.1	Use safe work procedures and protective equipment to ensure personal safety and that of others.....	105
5.2	Minimise generation of wastes and environmental impacts of testing	106
5.2.1	<i>Reduce the generation of wastes.</i>	106
5.3	Collect and/or dispose of all waste in accordance with environmental/quarantine requirements and enterprise procedures	107
5.3.1	<i>Safe storage of materials</i>	107
5.3.2	<i>General guidelines for the storage of dangerous chemicals</i>	108
5.3.3	<i>Waste disposal</i>	109
5.3.4	<i>General disposal procedures</i>	110
5.4	Care for and store equipment, used test pieces and back-up samples in accordance with enterprise procedures.....	111